


X01-W034

△			
△			
△			



CON.NO	QUAN	NAME	MATERIAL	STANDARD	DISPOSAL	REMARKS
A4	SCALE <input checked="" type="checkbox"/>	UNIT <input checked="" type="checkbox"/>	DATE 90.11.01	DESCRIPTION <b>CDD -4 0</b> Excess Gain— Sensing D istance		
APPROVED BY K.Matsumoto	CHECKED BY R.Kumo	DRAWN BY S.Nishimura	DESIGNED BY S.Nishimura	ITEM Excess Gain		
3RD ANGLE PROJECTION	OPTEX FA CO.,LTD.			DRAWING NO <b>X01-W034</b>		