



WIRING CHART			
P1	P2	P3	WIRE
6	1		RED SHIELD
22	6		RED CENTER
6	2		ORANGE SHIELD
9	3		ORANGE CENTER
2	2		WHITE SHIELD
5	4		WHITE CENTER
2	2		BLACK SHIELD
1	5		BLACK CENTER
8		1	BROWN
21		2	YELLOW
23		11	BLUE
8		8	WHITE SHIELD
18		9	WHITE CENTER
14		5	RED SHIELD
25		6	RED CENTER
14		12	ORANGE SHIELD
26		7	ORANGE CENTER