							\triangle							
						L								
Ga in														
	100													
	100													
Excess	10													
Щ Х														
	,													
	1									Opera	a t in g	Level		
	(ງ	1	2	3		4	 !	5		6		7	
	Ì	0 1 2 3 4 5 6 7												
				Se	ens ing	D is t	ance	e (m)						
CON.NO QUAN				NAME		MATERIA	ıL	STANDARD		ISPOSAL		REMARKS		
A4		SCALE		UNIT	DATE 96.10		DESCRIP	S T -4 0 0						
APPROVED BY		CHECKED BY		DRAWNED BY	DESIGNED BY		Excess Gain— Sensing Distance							
K.Matsumoto				S.Nishimura	S.Nishii	mura	ITEM	Excess Gain						
3RD ANGLE PROJECTION		SICK	SICK OPTEX			D.	DRAWING NO X36-W293							